

Screw-feed Drills

RAB

Atlas Copco screw-feed drills are ideal for heavy-duty drilling operations requiring high feed forces. They can also be used for reaming and tube-rolling.

- Reliable – Simple, reliable design.
- Constant speed – The speed governor keeps the drilling speed constant and reduces air consumption as power is reduced.
- Safer – The safety catch prevents accidental starting. The throttle is also self-closing.



Model	Forward	Reverse
RAB9	1.14 hp	0.74 hp
RAB12	2.0 hp	1.5 hp

Model	Free speed r/min	Capacity			Morse taper No.	Length feed mm	Height in	Weight lb	Hose dimension		Air consumption max output cfm	Distance centre to side mm	Air inlet thread NPT	Ordering No.
		Drilling mm	Reaming mm	Tapping mm					mm	in				
RAB9 VR003	300	23	23	16	2	75	10.4	20.9	13	1/2	47	40	1/2	8421 5109 37
RAB9 VR006	600	23	23	12	2	75	10.4	20.9	13	1/2	49	40	1/2	8421 5109 45
RAB12 L150	140	51	40	32	4	90	15.2	32.8	16	5/8	64	50	1/2	8421 5112 08
RAB12 L250	240	51	40	30	4	90	13.2	32.8	16	5/8	70	50	1/2	8421 5112 16
RAB12 L450	475	32	32	24	3	90	13.4	28.4	16	5/8	68	50	1/2	8421 5112 24

Accessories Included

Hose nipple

Optional Accessories

SQUARE DRIVE ADAPTER

Morse taper No.	Square drive in	Ordering No.
3	1	4021 0394 00
4	1	4021 0395 00



Square drive adapter